

Chesterfield County
Department of Building Inspection (804) 748-1057 www.chesterfield.gov/bi

	In Triassic Area	Outside Triassic Area
	(refer to Triassic map)	(refer to Triassic map)
New house	Soil test required. "Low" (1) 24" deep,	Soil test required. "Low" (1) 24" deep,
	"Low" (1) 24" deep,	"Low" (1) 24" deep,
	"Moderate" or higher (2)	Moderate or higher (2)
	engineer design	engineer design
Industrialized (modular) home or	No test required.	No test required.
manufactured home	Manufacturer's design, or	Manufacturer's design, or
	engineered design, or	engineered design, or
	24" deep cont footing	24" deep cont. footing
Addition to house with (potentially) habitable	Soil test required.	No test required.
space	"Low" (1) 24" deep,	Footing 24" deep
	"Moderate" or higher (2)	
	Engineer design	No testine a la
Addition to house without (potentially)	No test required.	No test required.
habitable space, screen porches, and	Footing 24" deep	Footing 24" deep
unheated (three season) porches		
Conversion of sunroom to Florida room	Engineer's sealed certification	Excavation required to verify
	of existing footings	18" deep existing footing - by
		County inspector
Detached garage with (potentially) habitable	Soil test required.	No test required.
space	Footing 24" deep	Footing 24" deep
Detached garage without (potentially)	No test required.	No test required.
habitable space	Footing 18" deep	Footing 18" deep
Decks	No test required.	No test required.
	Footing 18" deep	Footing 18" deep
Wood tool sheds	No test required.	No test required.
	See SHEDS	See SHEDS
		000 01.120
	No test as a sine d	No test negotiard
Metal carports and pre-fab metal sheds	No test required.	No test required.
	Engineer specified anchors	Engineer specified anchors
Pre-fab metal buildings	No test required.	No test required.
To tab metal buildings	Footing 18" deep	Footing 18" deep
	Li ooliig io deep	r rouning to deep

⁽¹⁾ LOW refers shrink swell potential, based on engineer's analysis in the soil report.(2) MODERATE OR HIGHER potential for shrink swell, based on engineer's analysis of the soil report. An engineered footing is required.